PCN Number:		201601200	20160120002					ate:	1/25/2016	
Title: Datasheet for									1,23,2313	
Customer Contact:		PCN Manager						Опа	lity Services	
Change 1		- Communicación					 	Quu	, 20. 1.002	
	sembly Site			Design	П	\neg	Wafer	Rum	n Site	
Assembly Process		S	\boxtimes	Data Sheet	Ħ	┪		Wafer Bump Site Wafer Bump Material		
Assembly Materials				Part number change	Ti	Wafer Bum			•	
Mechanical Specific				Test Site	Ti		Wafer Fab Site			
	/Labeling		Test Process	Ti	T	Wafer Fab Materials				
					Ti				Process	
		N	O	tification Details			•			
Descript	on of Change									
			ou	ncing an information only	no	otif	ication	etc.		
	Texas Instruments Incorporated is announcing an information only notification etc.									
The produ	ict datasheet(s) is being upda	ite	d as summarized below.						
The following change history provides further details.										
lia Tex	4.6									
TEX	AS TRUMENTS								TMP103	
	THOMESTE			SBOS545B – F	EBF	RUAR	Y 2011-RE	VISED JA	NUARY 2016	
Changes from Revision A (March 2011) to Revision B										
Added ESD Ratings table, Feature Description section, Device Functional Modes section, Application and										
Implementation section, Power Supply Recommendations section, Layout section, Device and Documentation										
Support section, and Mechanical, Packaging, and Orderable Information section										
Added SSDs, Servers, Telecom, Set Top Boxes, Low Power Environmental, and Sensors to Applications section 1										
-										
The datas	heet number v	vill be changing	1.							
Device Family		···· be enanging	Change From:			Change To:			To:	
TMP103			SBOS545A				SBOS545B			
111 100 SB00373B										
These cha	inges may he r	eviewed at the	А	atasheet links provided.						
	w.ti.com/prod		u	atasneet iinks provided.						
itcp.//ww	w.ti.com/prod	<u>ucc/1141/105</u>								
Reason f	or Change:									
		ct device chara	ct	oristics						
	•						***			
				ction, Quality or Reliabi			-			
	•	his is a specific	cat	tion change announcement	0	nly	v. There	e are r	no changes to	
the actua										
Changes	to product id	entification r	es	ulting from this PCN:						
None.										
Product	Affected:									
TMP103/		MP103AYFFT		TMP103BYFFR	TI	MР	103BYF	FT		
TMP103		MP103CYFFT		TMP103DYFFR		MP103DYFFT				
TMP103		MP103EYFFT		TMP103FYFFR			103FYF			
TMP1030		MP103GYFFT		TMP103HYFFR			103HYF			
11:11 103(J 1 1 1 1 1 1 1	10001111		1111 100111111		- 11 -	-001111			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
lapan	PCN.JapanContact@list.ti.com